R-Series
Issues and workarounds about DAW software

The following troubles may occur when using DAW software on Windows 10.

Products ;
  R8 / R16 / R24

Example of issues ;
 - R-series may not be recognized on DAW, i.e. R-series audio driver is not displayed at a list of audio
   devices.
 - An error may occur when R-series audio driver is selected from list of audio devices.
 - Sampling rate shown on the R-series display is unstable.

Those problems occur when FL Studio ASIO is installed in a PC.
If this kind of problem occurs, please try the following workaround.

 - Uninstall the FL Studio ASIO
   * It is not necessary to uninstall the FL Studio.
   Click "Start Menu" - Select "Settings" - Select "System" - Select "Apps & Features"
     - Select "FL Studio ASIO" - Select "Uninstall"
   * After the FL Studio ASIO was deleted from system, FL Studio needs to use R-series driver.